

# CAUTION!!!



Before proceeding to Step # 7, all parties involved in the foaming process and within a 25' radius should wear protective clothing, face shields, rubber gloves, protective hoods etc... All body parts and bare skin should be covered (as seen at left ).



7. Place nozzle into  $\frac{1}{4}$ " hole and apply foam according to directions on the container. As foam expands and exits the second relief hole, press finger against the hole to control flow of foam allowing the annular cavity to completely fill, and to allow gases to escape. **DO NOT COMPLETELY COVER THE HOLES.**